

Injectronics

TECHNICAL BULLETIN

HOLDEN – ASTRA

#T0099

Make: Holden

Model: Astra TS & X18XE1 engine

Subject: Engine surging between 40 – 80 klms and light throttle to 3000 RPM

TEST: Check data codes with a scan tool, are codes P0400& P1405 evident? With the vehicle at normal operating temperature, disconnect the wiring to the EGR valve & road test vehicle noting the performance of the vehicle, does the vehicle drive OK?

CAUSE: Fault may be due to a faulty EGR valve.

Replace EGR.