

*Inj*ectronics

TECHNICAL BULLETIN

HOLDEN – COMMODORE – VT

#T0108

Make: Holden

Model: Commodore VT

Subject: Engine stalling intermittently

TEST: Road test vehicle, the engine would stall intermittently, more evident on hot days.

FAULT: The fuel pump relay is faulty. It may cause an intermittent loss of 12V to the fuel pump.

Replace relay