

Injectronics

TECHNICAL BULLETIN

TOYOTA - LANDCRUISER

#T0119

Make: Toyota

Model: Landcruiser Turbo Diesel 2001

Subject: Engine cutting out

TEST: Check the Data codes. Are anti-theft fault codes stored? Check wiring & connector plug at injector pump for heat & vibration related damage.

CAUSE: The wiring plug connected to the injector pump can become loose or disconnected due to heat & or vibration causing the engine to stop.

Replace the terminals & fill the connector with resin.