

Injectronics

TECHNICAL BULLETIN

KIA – SPORTAGE

#T0127

Make: Kia

Model: Sportage 2000-2002

Subject: Lack of power, stalling and surging

TEST: Check O2 sensor operation. Voltage should cycle between 0 - 1V at 2000 RPM at operating temperature.

FAULT: Faulty O2 sensor operation has been seen to cause the above symptoms.

Replace O2 sensor.