

# *Injectronics*

## **TECHNICAL BULLETIN**

### **HOLDEN – BARINA**

#T0086

**Make: Holden**

**Model: Barina 2001**

**Subject: Service light reset**

Service light reset procedures are a common request of the Injectronics technical department and the 2001 Holden Barina is yet another addition to the list

The service indicator light is located in the trip meter / odometer window on the speedometer. When the vehicle is within one week or 500kms of its next service, the letters "InSP" will appear in the window for a few seconds after the ignition has been switched on.

The indicator can be reset by following this procedure;

1. Ignition off
2. Hold down the reset button (trip meter) while turning the ignition on
3. Wait until the letters "InSP" becomes a clear line
4. Release the button
5. The display should return to trip meter / odometer mode