

*Inj*ectronics

TECHNICAL BULLETIN

HOLDEN - BARINA

#T0101

Make: Holden

Model: Barina Combo (with AC)

Subject: No engine or A/C heater fan operation

TEST: Check the operation of the four control relays, one is located near the RH strut tower & the other 3 are located near the battery.

CAUSE: The relays near the battery can suffer from corroded terminals due to battery acid leakage.