

# *Inj*ectronics

## TECHNICAL BULLETIN

### HOLDEN – COMMODORE – VT / VX

#T0109

**Make:** Holden

**Model:** Commodore VT / VX

**Subject:** Poor fuel pump operation

TEST: Check fuel pressure, check voltage supply to fuel pump.

FAULT: Faulty or poor connection at the patch harness at the fuel pump.

Replace the patch harness.