

Injectronics

TECHNICAL BULLETIN

DAIHATSU - SIRION

#T0111

Make: Daihatsu

Model: Sirion 2000

Subject: No start, no spark, no injection

Test: No fault codes were evident.

Check for an inductive output signal from the crank angle sensor during crank.

Check engine cranking speed, approx 430 rpm with spark plugs fitted, no ignition or injection control evident.

Remove the spark plugs & recheck engine cranking speed approx, 480 rpm.

Ignition & injection control will be evident on the higher cranking speed.

Cause: The engine had the wrong grade/viscosity of engine oil in the engine resulting in lower than expected cranking speed.

Replace the engine oil with the correct grade/viscosity engine oil.