

Injectronics

TECHNICAL BULLETIN

HOLDEN – ASTRA TS

#T0121

Make: Holden

Model: Astra TS

Subject: Air mass meter fault

TEST: Engine stalling, poor engine performance & transmission shift quality. Inspect ECM for fault codes, Intake Air temp sensor & AMM codes logged.

FAULT: The air mass meter ground is open circuit. The AMM ground is via the engine control unit.

Splice a wire to the yellow wire pin2 at the AMM and attach it to a good chassis ground point.

If the car now runs ok, have the E.C.M repaired or replaced.