

*Inj*ectronics

TECHNICAL BULLETIN

HOLDEN – RODEO 2.6L

#T0122

Make: Holden

Model: Rodeo 2.6L

Subject: Poor fuel pump operation

TEST: Check fuel pressure, should be 250 +/- 20 kPa.

Check voltage supply to fuel pump, should be 12V.

FAULT: Faulty fuel pump harness connection at the fuel pump, repair/replace the harness connector.