

Injectronics

TECHNICAL BULLETIN

KIA – CARNIVAL

#T0126

Make: Kia

Model: Carnival 2001 2.5L V6

Subject: Engine runs lean on the rear cylinder bank (cylinder 2/4/6)

TEST: Check the diagnostic trouble codes with a scan tool.

Check the operation of the O2 sensors.

Check the operation of the AMM, output signal 0.6-0.8 volts @ idle.

FAULT: If AMM output signal is low, it causes the engine to run lean on the rear cylinder bank.

Replace the AMM.