

Injectronics

TECHNICAL BULLETIN

HOLDEN – RODEO TF

#T0093

Make: Holden

Model: Rodeo TF 3.2L V6 1998

Subject: Engine hard to start / wont start

TEST

- Cranking the engine the injectors will pulse once.
- Cranking the engine for 5-10 seconds the engine may start.
- The engine cranking speed is good.

FAULT

- The battery supply voltage to ECM is low.

Replace the battery