

Injectronics

TECHNICAL BULLETIN

HONDA – PRELUDE

#T0123

Make: Honda

Model: Prelude 1989

Subject: Intermittent no start

TEST: Check power to ECM pins A13/15 & fuel pump.

FAULT: Faulty main relay located behind the fuse panel right hand lower dash.